FORM COMP AA

(sec Rules 253 (c), 254 (c) (iii), 254 (80 255 (1) (iv))

REPORT ABOUT THE MOTOR VEHICLES ACCIDENTS

1	Name of the Police Station	Sonkhed dist.Nanded
2	CR.NO./TAR No./SDE No.	42/2023 U/S 279,304(a) of I.P.C
3	Date, Time and Place of the accident.	02/04/2023 at 14.00 hrs Nanded to Latur road near Janapuri Tq Loha dist. Nanded.
4	Name of the Injured / Deceased	Shivaji Ramji Jadhav age 24 year r/o Pimparaneadi Tq Loha dist. Nanaded
5	Name of Hospital to Which he/she was removed	Govt. Hospital Nanded
6	Number of vehicles and type of the vehicle	MH 42 BF 1618 Tipper
7	Name and address of the Driver of the vehicle with particulars or Driving License of the said Driver and the address of the Issuing Authority of the said Driving License. The number of Badge in case of Public Service Vehicle and the address of the Issuing Authority of the said Badge.	Ulhad Maroti Rathod age 41 year r/o Nipani Sawargaon Tq. Kandhar dist. Nanded MH 26 20020009698 RTO Nanded
8	Name and Address of the Owner of the vehicle as it stands on the date of the accident.	Satish Vishnu Bandgar r/o Bandgar wadi Tq. Iandapur dist. Pune
9	Name and address of the insurance Company with whom the vehicle was insured and the Divisional office of the said insurance Company.	Reliande general insurance comp.ltd.
10	Number of Insurance Policy/ Insurance Certificate and the date of Validity of the insurance Policy/ Insurance Certificate.	711622223340001974 30/11/2023
11	Action taken if any and the result there of	An offence has been registered against the accused. After completion of investigation Charge-sheet has been submitted.

Inspector of Police
Police Station Sonkhed
Dist. Nanded (M.S)

जबाब दिनांक 03/04/2023

मी, रामजी दिनाजी जाधव वय 50 वर्ष व्यवसाय शेती राहणार पिंपरणवाडी ता.लोहा जि.नांदेड मोबाईल नंबर 9545324866

समक्ष पोलीस स्टेशन सोनखेड येथे हजर येवुन तक्रारी जबाब देतो की, मी वरील ठिकाणचा राहाणारा असुन मला दोन मुले 1.शिवाजी रामजी जाधव वय 24 वर्ष 2.पांडोजी रामजी जाधव असे होते. माझा मुलगा शिवाजी हा ऑन लाईन आधार कार्ड काढणे व सेतु सुविधा चे खेडोपाडी जावुन शासकीय योजनेचे ऑन लाईन काम करण्यासाठी खेडोपाडी नेहमी फिरत होता. मी व माझा मुलगा पांडोजी आम्ही दोघे शेती व्यवसाय करुन पोट भरतोत.

दिनांक 02/04/2023 रोजी माझा मुलगा शिवाजी रामजी जाधव हा सकाळी अकरा वाजताचे सुमारास त्याचे सेतु सुविधाचे आधार कार्ड लिंक करण्याचे काम करण्यासाठी जानापुरी बामणी खरबी गावांत जात असल्याचे मला सांगितले व तो त्याचे मोटार सायकल क्रमांक MH26BV9489 वर गेला.

दुपारी दोन वाजताचे सुमारास मी सोनखेड येथे असतांना आमचे गावांतील सरपंच शिवाजी जाधव यांनी मोबाईल फोनवर कळविले की, माझा मुलगा शिवाजी हा खरबी पाटीकडून जानापुरी कडे येत असतांना त्याचे मोटार सायकल ला हायवा टीपर ने समोरा समोर धडक दिली आहे तो गंभीर जखमी झाला उपचारासाठी सरकारी दवाखाणा विष्णुपूरी नांदेड येथे घेवुन जात असल्याचे सांगितले. सोनखेड येथुन मी, आमचे गावांतील भिवा मानसिंग जाधव, राजेश बाजीराव जाधव व इतर गावांतील बरेच लोक खरबी पाटीकडे पाठविले. त्यानंतर वरील लोकांनी मला सांगितले की, शिवाजी यास सरकारी दवाखाना विष्णुपूरी नांदेड येथे उपचारासाठी घेवुन आणले असता त्यांचे डोक्यात गंभीर मार लागलेला त्याचे डोके फूटून हाता पायाला जबर मार लागुन तो मृत अवस्थेत असल्याचे तपासुन दिनांक 02/04/2023 रोजी 16.21 वाजता डॉक्टरांनी घोषीत केले.

माझा मुलगा शिवाजी याचे अपघात करणारे वाहना बाबत व घटने बाबत आमचे गावांतील वरील लोकां कडून मला समजले की, माझा मुलगा शिवाजी रामजी जाधव वय 24 वर्ष हा त्याचे मोटार सायकल क्रमांक MH26BV9489 वर खरबी पाटी येथुन जानापुरी कडे येतांना वाडी पाटीच्या उड्डाण पुलाचे व साईड रोड चे रुंदीकरणाचे काम चालु असल्याने तसेच खरबी पाटी येथे रोड बदलीसाठी डिव्हाईडर नसल्याने पर्यायी खरबी कडून येणारी वाहणे ही एक मार्गी जानापुरी पर्यत यावे लागते त्याप्रमाणे माझा मुलगा दिवसा चे वेळी प्रखर उन्हात दुपारी दोन वाजताचे सुमारास गांवी येण्यासाठी एकमार्गी रोडने जानापुरी पर्यत येत असतांना खरबी पाटी ते गॅस गोडावुन चे दरम्यान जानापुरी शिवारात जानापुरी कडून नांदेड कडे रोडने येणारे हायवा क्रमांक MH42BF1618 चा चालक त्याचे नांव उल्हास मारोती राठोड राहणार नेपानी सावरगांव ता.कंधार याने त्याचे ताब्यातील हायवा ही हयगई व निष्काळजीपणे भरधाव वेगात चालवित येवुन माझा मुलगा शिवाजी रामजी जाधव हा रोड च्या बाजुने त्याचे मोटार सायकल वर येत असतांना हायवा चालकाने त्यास समोरा समोर जबर धडक देवुन त्यास गंभीर जखमी करुन माझे मुलाचे मरणास कारणीभुत झाल वरील हायवा क्रमांक MH42BF1618 चे चालकाविरुध्द योग्य ती कायदेशिर कार्यवाही करण्यात यावी.

माझा जबाब माझे सांगणे प्रमाणे संगणकावर टाईप करण्यात आला तो वाचुन पाहीला बरोबर व खरा आहे.

समक्ष. हा जबाब दिला सही

ीस ठाणे अमलदार
ीस स्टेशन, सोनखेड.

रामजी

Form: ii-1

CRIME DETAILS FORM

घटनास्थळ पंचनामा/ गुन्हयाच्या तपशीलाचा नमुना

1. State-- महाराष्ट्र Dist-- नांदेड P.S-- सोनखेड Fir/Proceeding/G.D.No-- 42/23 Year-- 2023 Date 03/04/2023
राज्य :— महाराष्ट्र जिल्हा :— नांदेड पोलीस ठाणे :— पहिली खबर क्र./कार्यवाही क्र. वर्ष तारीख

2. Act and Sections -------- भादंवि कलम 279, 304 (अ)
- अधिनियम व कलमे :—

3. The place of Occurrence shown by :-
घटनेचे ठिकाण दाखविण्याचे.

Name :- ------ बालाजी नारायण बोईरे ---- Father's/Husband's Name :------ नारायण बोईरे
नाव :— पित्याचे/पतीचे नाव

Address -------- रा. शेलगाव ता. लोहा मो. न. 9422535475
पत्ता :—

4. TYPE OF CRIEM (All including M.O. Crime) :
गुन्हाचा प्रकार (गुन्हयाच्या सर्व पध्दती सह) :

i) * Major Head-- अपघाताने मृत्यु ---- ii) Classification of Major Head:------ प्रतिकाराने प्राणांतिक अपघात
प्रधान शीर्ष : प्रधान शीर्षचे वर्गीकरण :

iii) * Mathod (s) पध्दती:—
१. यातील मयत हा खरबी पाटी समोर डिव्हायडर नसल्याने पर्यायी एकमार्गी
२. खरबी ते जानापुरी कडे त्यांचे मो.सा. वर येत असतांना यातील आरोपी टिपर
३. चालक क्र MH 42 बी एफ हा हयगयी व निष्काळजीपणे चालवुन मयतास समोरासमोर 1818

iv) * Conveyances used : जबर धडक एम एच 42 बी एफ
वापरलेली वाहने: — देवुन मयताचे मरणास कारणीभुत झाला.

v) *Character assumed : ------ —
केलेले वेषांतर/केलेली बतावणी : —

vi) * Language/ S. lang. used: ------ —
वापरलेली भाषा/बोली भाषा : —

vii) * Special Feature-1 : ---- सदरचा अपघात राष्ट्रीय महामार्ग क्र. 361 वर
विशेष वैशिष्ट्ये १ : —

viii) * Special Feature-2 : ------ —
विशेष वैशिष्ट्ये २ : —

* Special Feature-3 : ------ —
विशेष वैशिष्ट्ये ३ : —

ix) Type of place of Occurrence: -- सदरचे घटनास्थळ जानापुरी शिवारातील माधवराव कदम यांचे शेता समोर नांदेड ते लोहा रोडवर गॅस गोडावुन 300 मिटर खरबी पाटी 500 मीटर दरम्यान
घटनेच्या ठिकाणाचा प्रकार: —

x) Type of property involved (4 Types): Major head of the property to be filled): ------
अंतर्भूत मालमत्तेचे प्रकार : —

१) .... २) ....

३) .... ४) ....

शिवाजी

5. **Particulars of the victims (Attach separate sheet, if required):-**
बळींचा तपशील (आवश्यक असल्यास स्वतंत्र कागद जोडावा) :

Sr. No. अ. क्र	Full Name संपुर्ण नाव	Date/ Year of birth जन्मतारीख / वर्ष	Sex लिंग	Nationality राष्ट्रीयत्व	Religion धर्म	Whether SC/ST जाती/ जमाती	Occupation व्यवसाय	Address पत्ता	Injury: Grievous/ Simple दु:खापत गंभीर/ साधी	Means साधने / हत्यारे
	शिवाजी रामजी जाधव रा. पिंपरणवाडी ता. लोहा	24 वर्ष	पुरुष	भारतीय	हिंदू	—	—	पिंपरणवाडी ता. लोहा	मयत	हायवा क्र. MH42 BF16

6. Motive of Crime गुन्हयाचा हेतू

स्वतःचे ताब्यातील वाहन हे अविचाराने चालविले.

7. Details of properties Stolen/Involved(Use appropriate prescribed forms (s) and attach) :
चोरीच्या / अंतर्भूत मालमत्तेचा तपशील (योग्य नमुना वापरावा व सोबत जोडावा)

8. Description of the place of occurrence :

घटनेच्या जागेचे वर्णन :—

आम्ही सपोनि विशाल भोसले पो.स्टे. सोनखेड पंचा समक्ष पो.स्टे. सोनखेड गु.र.क्र. 54/2023 क. 279, 304(A) भादंवि गुन्ह्याचा घटनास्थळ पंचनामा करतो की, सदरचे घटनास्थळ हे नानापुरी ते खरबी वाटी रोड वर असून सदरचा सी-सी रोड असून सदर सी.सी रोड वर भारत गॅस गोडाऊन नानापुरी पासून 300 मिटर अंतरावर असून सदरचा सी सी रोड हा दक्षिण उत्तर असून दक्षिणेस नानापुरी कडे जाणारा रोड व उत्तरेस खरबी वाटी कडे जाणारा सी. सी रोडवर घटनास्थळ असून सदर सी.सी

शिवाजी

9. Description of the place of occurrence (Contd) :

घटनेच्या जागेचे वर्णन (पुढे चालू)

MH42BF1618 ही आलापुरी कडून (लोहा ते नांदेड) रोडने रोडवर हायवा क्र जात असतांना तसेच सदर गुन्ह्यातील मयत हा खरबी पाटी येथे रोड डिव्हाईडर नसल्याने एक मार्गी खरबी पाटी ते आलापुरी कडे रोडच्या डाव्या बाजूने डिव्हाईडर लगत च्या साईडने येत असतांना सदरच्या अपघात हा सी. सी. रोडच्या मध्यभागी घडलेले ठिकाण [illegible] दिसत आहे. सदर रोडच्या पश्चिम बाजूस सी. सी. रोड लगत मोटार सायकल ॲसेसरिज फुटलेले तुटलेले तुकडे पडलेले दिसत आहे.

सदर रोड हा मध्य भागी डिव्हाईडर चा असून सदरचे डिव्हाईडर हे 6 इंच उंचीचे सी. सी. चे असून मध्यभागी मोकळा स्पेस व माती टाकलेली दिसत आहे त्या पलिकडे रोड ची दुसरी बाजू नांदेड कडून लोह्याकडे जाणारे रोड ची वाहतूक मार्ग दिसत आहे.

सदर घटनास्थळाचे रोड ची रुंदी 30 फुट असून बाजूस दोन्हा रोड व रोड रुंदीकरणाचे कडेने रोड च्या बाजूला टाकलेले दिसत आहेत.

सदर घटनास्थळाचे ठिकाणापासून उत्तरेस खरबी पाटी 300 मिटर अंतरावर पश्चिमेस खरबी कडे जाणारा रोड असून सदर पाटी समोर महामार्ग विस्तारीकरणाचे गुणाजी पेट्रोलियम डेरका पाटी चे पुढे चालू असून सदर ठिकाणा पासून नांदेड व लोह्या कडील एकमार्गी वाहतूक चालू आहे. सदर घटनास्थळाचे ठिकाण ते खरबी पाटी 300 मीटर व गुणाजी पेट्रोलपंप 200 मिटर अंतरावर डिव्हाईडर दिसत आहे.

सदर घटनास्थळाची चतुःसीमा पाहता पुर्वेस सी. सी. रोड व रोडच्या आतील दुभाजक त्यालगत लोह्याकडे जाणारा सी सी रोड व त्या पलिकडे असम कंबळे यांचे शेत आहे पश्चिमेस सी. सी. रोड त्यालगत पेव्हरब्लॉक व बाजूस सिमेंट कडे त्या पलिकडे माधवराव कदम आलापूरी यांचे शेत आहे दक्षिणेस लोह्याकडून नांदेड कडे जाणारा सी सी रोड उत्तरेस नांदेड खरबी पाटी कडे जाणारा सी सी रोड आहे.

सदर घटनास्थळाचे अक्षांश 19.072015° रेखांश 77.24863° आहे.

सदर घटनास्थळा वरील हायवा क्रमांक MH42BF1618 व अपघात ग्रस्त मो. सा MH26BV9494 ही वाहने घटनास्थळावरून सुरक्षिततेच्या दृष्टीकोनातून व पोलिस ठाण्यात आणण्यात आलेली आहेत. सदर मयताची मो. सा क्र MH26BV9494 ची पाहणी केली असता इंजिन पासून दोन भाग तुटून पडलेले दिसत आहेत तसेच पाठीमागील भाग तुटलेला व मो. सा ची फायबर ॲसेसरिज तुटलेली फुटलेली दिसत आहे.

सदर अपघातातील वाहन हायवा क्र MH42BF1618 ची पाहणी केली असता सदरची हायवा ही 10 टायर्स ची असून हवा सुरक्षित दिसत आहे सदर हायवाच्या समोरील रेडियटर प्रोटेक्शन तुटलेले दिसत असून रेडियटर चे ड्रायव्हर साईड आतील बाजूस काळपट रक्ताचे माखलेले दिसत आहे तसेच बंम्पर वाकलेले कलर पेंट पुसलेले दिसत आहे ड्रायव्हर साईड हेड लाईट फुटलेला दिसत आहे. ड्रायव्हर साईडने पाहणी करता टायर वर व गार्डवर काळपट रक्ताचे डाग दिसत आहेत तसेच हायवाचे ड्रायव्हर साईड चे चेसिसवर काळपट रक्ताचे डाग चरबटलेले दिसत आहे.

सदरचा पंचनामा हा पंचानी वाचून पाहून तो सत्य असल्याची खात्री करून स्वाक्षरी केली.

शिवाजी

कृपया मागे पहा

9 नकाशा Map



10 Dacsription of physical evidence from the sce4nce of crime for the property recovered/ seize for the purpose of investigation :-

तपासकामी प्रत्यक्ष पुरावा म्हणून गुन्हयाच्या जागेवरून मिळलिल्या/ जप्त केलेल्या मालमत्तेचे वर्णन :

11.Date and time of panchnama Time

घटनास्थळ पंचनाम्याची दिनांक 04/04/2023 वेळ 18:00 ते 19:00 पर्यंत

12.Name of panchas Signature of panchas

पंचाची नावे पंचाच्या सहया

१ बालाजी नारायण नरिटे वय 52 वर्ष रा. शेलगाव ता.लोहा

पत्ता व्यवसाय शेती मो.न. 9922352575

२ शिवाजी माधवराव जाधव वय 36 वर्ष व्यवसाय शेती

पत्ता रा. पिंपळगाव ता. लोहा मो. 7507001371

Name and signature of Investigation officer

तपासीक अंमलदाराची सही

Date 04/04/2023

Name नाव विशाल दिपक भोसले

Rank पदनामा सपोनि B. No. if any ब.न.

पो.स्टे. सोनखेड

A.-(Y)-176-(20,000 Sets)-03-2021.
[.. G. D.. No. 733/33. dated 16-6-41 and
R.. H. and L. G. D. No. 733/33. dated 11-12-47.
[de Surgeon General with the Govt. of Maharashtra, Bombay's
Letter No. FRM/1462/19357/1. dated 4-7-62.]

MLPM NO:- 317/2023
Date : 02/04/2023

C. M. 67 e.

Memorandum of a Post-mortem examination held at Dr. SCGMC, Nanded. Dispensary / Hospital

On the dead body of Shivaji Ramji Jodhav of Village / City Pimpalranwadi

Taluka Loha District Nanded. by [Dr. G. B. Mishra] [Dr. N. V. Mandle]

I. General Particulars—

1. (a) By whom was the corpse sent ? ASI M. K. Gotamwad . PS-Nanded Gramin.

(b) Name of place from which sent.
(c) Distance of place from which sent.
} Dr. SCGMC, Nanded.

2. By whom was the corpse brought ?
3. By whom identified ?
} PC J. R. Thakur , B.NO-2756 . PS-Nanded Gramin.

4. The date, hour and minute of its receipt. 02/04/2023 at 06:00 PM.

(a) The date, hour and minute of beginning post-mortem examination. 02/04/2023 at 06:15 PM.

(b) The date, hour and minute of ending post-mortem examination. 02/04/2023 at 07:15 PM.

5. Substance of accompanying Report from Police Officer or Magistrate, together with the date of death if known. Supposed cause of death or reason, for examination. AS per police inquest & requisition letter, history of road traffic accident on 02/04/2023 at 14:00 hours. For treatment purpose, brought at government hospital vishnupuri, Nanded. After examination by doctor on duty, declared brought dead on 02/04/2023 at 16:21 hours.
Supposed cause of death - road traffic accident.

पोलीस ठाणे सोनखेड
आवक/जावक क्र. 323/23
दिनांक 18/04/2023.

6. If not examined at Dispensary or Hospital—

(a) Name of place where examined.

(b) Distance from Dispensary or Hospital—

(c) Reason why the body was not sent to the Dispensary or Hospital—

Not applicable.

II. External Examination—

7. Sex, apparent age, race or caste. Male, 24 years old.

Description of clothes and of ornaments on the body. Maroon coloured shirt, black jeans pant, black waist belt, blue banyan, blue underwear, red waist thread, hospital label on left-

8. *Condition of the clothes*— whether wet with water, stained with blood or soiled with vomit or foecal matter. Intact, blood stains present over shirt and pant at places. handed over to police constable on duty.

9. Special marks on the skin such as scars, tattooing etc., any malformations peculiarities, or other marks of identification. State of the teeth. Body identified by police constable on duty. Teeth- ~~intact~~ Mandle, fractured, separated from socket.

In newly born infants, the length and (if possible) the weight of the body to be recorded together with the state of the hair, nails and umblical cord, its length, whether placenta is attached or not, if present, its size and condition. Not applicable.

10. *Condition of body*— whether well-nourished, thin or emaciated, warm or cold.	Averagely built, cold.
11. *Rigar Mortis*—Well Marked, slight or absent; whether present in the whole body or part only.	Absent in the whole body.
12. Extent and signs of decomposition, presence post-mortem lividity of buttocks, loins, back and thighs or any other part. Whether bullae present and the nature of their contained fluid. Condition of the cuticle.	No signs of decomposition. Postmortem lividity present over posterior aspect of body except pressure areas, not fixed.
13. *Features*—Whether natural or swollen, state of eyes, position of tongue: nature of fluid (if any) oozing from mouth, nostrils or ears.	Facial features - disfigured. Refer to the injury no (1) mentioned in column no (17).
14. *Condition of skin*— Marks of blood etc. In suspected drowning the presence or absence of cutes anserina to be noted.	Dry, pale.

15. Injuries to external genitals. Indication of purging.

No injuries
No purging.

16. ***Position of limbs***—Especially of arms and of fingers in suspected drowning the presence or absence of sand or earth within the nails or on the skin of hands and feet.

Straight.

17. ***Surface wounds and injuries***—Their nature, position, dimensions (measured) and direction to be accurately stated-their probable age and causes to be noted.

If bruises be present what is the condition of the subcutaneous tissues ?

(*N.B.*—(When injuries are numerous and cannot be mentioned within the space available they should be mentioned on a separate paper which should be signed).

① Crush injuries present over head, face of size 22cm x 6cm. Skull bo base of skull fractured in pieces, me torn, brain matter absent. Facial bones (maxilla, mandible, nasal bones) crush whole teeth fractured, separated from soc eyes crushed, eyeballs bulging out, both & lower lips lacerated, tongue-lacerated

② Graze abrasion present over right shoulder on posterior aspect of size 4cm X 3cm, di downward laterally, red.

③ Graze abrasion present over left hand dors aspect of size 6cm x 4cm, directed upward, r

④ Multiple graze abrasion present over anter aspect of chest of size 24cm x 22cm, dire in various direction, red.

⑤ Lacerated wound present over right leg on anterior aspect, upper part of size 6cm x 3 bone deep, margins irregular, red.

⑥ Graze abrasion present over left leg upper p and left knee anteriorly of size 12cm x 8cr directed upward, red.

⑦ Graze abrasion present over right leg lower anterior aspect of size 18cm X 3cm, directe downward, red.

⑧ Graze abrasion present over left leg ante medial aspect of size 6cm X 3cm, directe downward, red.

18. Other injuries discovered by external examination or palpation as fractures etc.

① Right tibia, fibula fracture ② Right femur fracture ③ Left femur fracture. ④ Right ra -ulna & left radius-ulna fractured & disloc All fracture margins irregular & infiltrated wi blood.

(a) Can You say definitely that the injuries shown against serial Nos. 17 and 18 are ante mortem injuries?

Yes, it is antemortem.

III. Internal Examination—

19. *Head*—

(i) Injuries under the scalp, their nature.

(ii) *Skull*—Vault and base-describe fractures, their sites, dimensions, directions, etc.

(iii) *Brain*—The appearance of its coverings, size, weight and general condition of the organ itself and any abnormality found in its examination to be cerefully noted (weight M. 3 grams F. 2.75 grams).

} Refer to the injury no. 1 mentioned in the column no. 17.

20. *Thorax*—

(a) Walls, ribs, cartilages Intact, no fracture.

(b) Pleura ~~Intact~~, each cavity contains about 500 ml blood.

(c) Larynx, Trachea and Bronchi. Intact, no foreign body.

(d) Right Lung
(e) Left Lung
} Intact, edematous, pale
Contusion present over surface at places.

(f) Pericardium Intact

(g) Heart with weight
(h) Large Vessels
} Intact, blood & blood clots present.

(i) Additional remarks. — None.

21. *Abdomen*—

Walls Intact

Peritoneum
Cavity } Intact, about 1 litre of blood present.

Bucal Cavity, teeth, tongue and Pharynx. Refer to injury no. 1 mentioned in column no. 17.

Oesophagus Intact.

Stomach and its contents About 10 cc blackish fluid present with kerosene li[ke] smell perceived, mucosa - rugous, hard.

Small intestine and its contents.
Large intestine and its contents. } Intact, partly filled with feces & gases.

Liver (with weight) and gall bladder. contusion present over left lobe.

Pancreas and Suprarenals Intact, pale.

Spleen with weight Lacerated into pieces., blood clot adherent to marg[in]

Kidneys with weight Intact, pale.

Bladder Intact, empty.

Organs of generations Intact.

Additional remarks with where possible, medical officer's deduction from the state of the contents of the stomach as to time of death and last meal. Not commentable

State which viscera (if any) have been retained for chemical examination and also quote the numbers on the bottles containing tha same. } Viscera preserved, Bottle no ① stomach & loop of in[testine] with its content. Bottle no ② 1/3rd of liver, 1/2 of spl[een], 1/2 of each kidney. Bottle no ③ Blood for chemi[cal] analysis. All bottles of viscera packed, seal[ed], labelled, signed & handed over to police constable on duty.

22. *Spine and Spinal Cord— Cervical spine crushed at C_1, C_2, C_3 level. Thoracic spine transected at T_2-T_3 level. Fracture margins irregular, infiltrated with blood, hemorrhage present in surrounding paraspinal tissue.

Opinion as to the cause probable cause of death. "Death due to multiple injuries."

N.mandle..
[Dr. N.V. Mandle]
Resident Doctor
Dept. Of Forensic Medicine
Dr.S.C.Govt.Medical College
Vishnupuri,Nanded-431606

[Dr. G.B. Mishra]
Resident Doctor
Dept. Of Forensic Medicine
Dr.S.C.Govt.Medical College
Vishnupuri,Nanded-431606

Dated 02/04/2023 (Signature)

*This Spinal Cord need not be examined unless there are any indications of disease. Strychnia poisoning or injury.

Note— The report must be written and signed immediately after the examination. Medical Officers will at once despatch a duplicate copy to the Civil Surgeon of their district for record in his office.

Great care should be taken not to cut the viscera before they have been inspected in situ.

MLPM No. 317/2023 02/04/2023

Place Dispensary / Civil Hospital Dr. SCGMC, Nanded. 20

Forwarded to the Police Sub-Inspector PS- Nanded Gramin.

for information with reference to his No. FMLC/2400/23 of 02/04/2023

2. Viscera has been preserved. It may please be stated *Immediately* whether examination by the Chemical Analyser is necessary or ~~it is to be destroyed.~~

[Dr. N.V. Mandle]
Resident Doctor
Dept. Of Forensic Medicine
Dr.S.C.Govt.Medical College.
Vishnupuri.Nanded-431606

[Dr. G. B. Mishra]
Civil Surgeon or M. M. S. Officer
Resident Doctor
Dept. Of Forensic Medicine
Dr.S.C.Govt.Medical College.
Vishnupuri.Nanded-431606

Copy forwarded with compliments to the Civil Surgeon. for information.

Forensic Medicine Dept. Dr.S.C.G.M.C. Vishnupuri Ned.-431606. सत्यमेव जयते

M. M. S. Officer

Seen and examined by the Civil Surgeon. on

20

Remarks of the Civil Surgeon. (if any)

Civil Surgeon